GAATN Network Status Report:

Damages or unexpected project issues since previous meeting

Date	Ring	Entities Affected	Description (Project or Repair)	Root Cause	Resolution
6/26/22	A1N	DIR	Broken strand at case A1N51	Unknown	Brycomm performed an emergency repair splice on 6/27 on DIR strand at case A1N51 no reason for the broken strand was found. The strand was broken in the tray. NM spending authority.
6/4/22	SRN	AISD/UT	Atkinson Road around Reagan HS and Gullet ES	Possible lightning strike	Brycomm performed an emergency repair on 6/4 to roll AISD and UT onto other strands. An emergency permanent repair was performed on 6/14 under NM spending authority.
6/2/22	C1S	None	S. 1st Street/Eberhart Lane	During routine ring inspection, Brycomm found that C1S was torn down and laying in a grassy area between two poles. It may have been hit by a conex or job trailer that was parked within the corner lot.	Brycomm didn't find any visible damage on the cable, only the strand was snagged and pulled out of the false dead-end preform. They sent a crew out to make the necessary repairs.
3/14/22	C2S	Travis County	FM620/Mansfield Dam	Vehicle hit pole on the southside of FM620 causing the aerial crossing to be torn down.	Maintenance contractor dispatched to complete temporary repair. A claim has been filed with the responsible party's insurance company.

Updated 09/16/2022

Date	Ring	Entities Affected	Description (Project or Repair)	Root Cause	Resolution
1/1/22	C1N	All	1202 E. St. Johns Avenue emergency repair	Gunshot on NYE	Maintenance contractor had to wait until 1/6 to perform Maintenance contractor had to wait until 1/6 to perform emergency repair due to safety issues on the ground. A permanent repair has been proposed. A GAATN property insurance claim will be filed.
10/28/21	B2S	Travis County	Oak Ranch Community Pierce Lane and Paseo Nuevo Circle	Management was contacted by a community manager who alerted that GAATN cable was hanging low at both entrances to their neighborhood. It appears that an unknown vehicle struck GAATN FOC at the entrances causing it to sag.	Maintenance contractor was dispatched and repaired/raised back to original height. The cable was not damaged.
10/18/21	B1N	All	11604 Stonehollow Emergency repair	FOC cut by unknown person(s) possibly looking for copper cable. This is the second cut by an unknown person at this same location. The first one happened in July. This location is behind abandoned warehouses which have now been demolished.	In July, the maintenance contractor was able to move some slack and they did the same thing for the second repair; a permanent repair has been approved by the Board and an insurance claim is in process.