GAATN Network Status Report:

Damages or unexpected project issues since previous meeting

Date	Ring	Entities Affected	Description (Project or Repair)	Root Cause	Resolution
10/18/21	B1N	All	11604 Stonehollow Emergency repair	FOC cut by unknown person(s) possibly looking for copper cable. This is the second cut by an unknown person at this same location. The first one happened in July. This location is behind abandoned warehouses which have now been demolished.	In July, the maintenance contractor was able to move some slack and they did the same thing for this week's repair, however there will most likely be a permanent repair needed and possibly an insurance claim.
10/28/21	B2S	Travis County	Oak Ranch Community Pierce Lane and Paseo Nuevo Circle	Management was contacted by a community manager who alerted that GAATN cable was hanging low at both entrances to their neighborhood. It appears that an unknown vehicle struck GAATN FOC at the entrances causing it to sag.	Maintenance contractor was dispatched and repaired/raised back to original height. The cable was not damaged.